First Quarter 2007 Groundwater Monitoring Report Former Weber Aircraft Facility Burbank, California



First Quarter 2007 Groundwater Monitoring Report Former Weber Aircraft Facility Burbank, California

Prepared for
P. H. Burbank Holdings, Inc.

Project No. 40641

March 2007



Burns & McDonnell Engineering Co., Inc. 393 E. Grand Ave., Ste. J South San Francisco, CA 94080

Signature Page

Simon Barber

Project Geologist

Gary P. Messerotes, PG

5650

Senior Project Manager

TABLE OF CONTENTS

1.0	INTRODUCTION	ı
2.0	BACKGROUND	l
2.1	PREVIOUS ENVIRONMENTAL ACTIVITIES.	2
3.0	GEOLOGY/HYDROGEOLOGY	1
3.1	REGIONAL HYDROGEOLOGY	1
3.2	TOPOGRAPHY AND SURFACE DRAINAGE	
3.3	SITE SPECIFIC HYDROGEOLOGY	
3.4	SITE CONDITIONS	5
4.0	GROUNDWATER SAMPLING ACTIVITIES	7
4.1	WELL GAUGING PROCEDURES	
4.2	WELL PURGING PROCEDURES	
4.3	PURGE WATER DISPOSAL	
4.4	GROUNDWATER SAMPLING	
4.5	WELL DEVELOPMENT & SAMPLING	
4.6	QUALITY CONTROL SAMPLING	,
5.0	GROUNDWATER FLOW CONDITIONS	•
6.0	ANALYTICAL RESULTS10)
6.1	Title 22 Metals)
6.2	EMERGING CHEMICALS	
6.3	VOLATILE ORGANIC COMPOUNDS	
6.4	INORGANIC COMPOUNDS, ANIONS, DISSOLVED OXYGEN, AND SUFIDES	
6.5	QUALITY CONTROL SAMPLES	5
7.0	SUMMARY AND CONCLUSIONS 15	5
7.1	METALS	
7.2	EMERGING CHEMICALS	
7.3	VOLATILE ORGANIC COMPOUNDS	
7.4	INORGANIC COMPOUNDS, ANIONS, SULFATES, DISSOLVED OXYGEN	7
LIST	OF TABLES	
Table	1 Cumulative Groundwater Elevations Data	
Table		١,
Table		
1 adie	and Chloride – 1 st Quarter 2007	,
Table		
Table		

LIST OF FIGURES

Figure 1	Site Location Map
Figure 2	Groundwater Elevation Map – January 2007
Figure 3	Concentration of Total Chromium in Groundwater – January 2007
Figure 4	Concentration of Hexavalent Chromium in Groundwater – January 2007
Figure 5	Concentration of PCE in Groundwater – January 2007
Figure 6	Concentration of TCE in Groundwater – January 2007
Figure 7	Concentration of 1,1-DCE in Groundwater – January 2007
Figure 8	Concentration of Nitrate as (N) in Groundwater – January 2007

LIST OF APPENDICES

Appendix A Groundwater Sampling Forms – 1st Quarter 2007

Appendix B Compact Disc (hard copies only) of Analytical Reports and Chain-of-Custody Form, Title 22/CAM 17 Metals and Volatile Organic Compounds

- 1st Quarter 2007 and Laboratory Reports and Chain-of-Custody Form,
Dioxins/Furans - 1st Quarter 2007

Appendix C Burns & McDonnell's QA/QC Review of Analytical Data

1.0 INTRODUCTION

This groundwater monitoring report for the former Weber Aircraft Facility (Site) is being submitted in response to correspondence from the California Regional Water Quality Control Board – Los Angeles Region (Water Board) requesting the initiation of a quarterly monitoring program to determine if volatile organic compounds (VOCs), heavy metals, and or emerging chemicals are present at the Site. P.H. Burbank Holdings, Inc., has contracted for environmental consulting services with Burns & McDonnell Engineering Company, Inc. (Burns & McDonnell) to perform this scope of work.

2.0 BACKGROUND

The Site is located at 2820 North Ontario Street (Parcel 1) and 300 San Fernando Boulevard (Parcel 3), in Burbank, California (Figure 1). The Site is bounded on the southwest by the former Kahr Bearing Facility and San Fernando Boulevard, on the west by North Ontario Street, a building to the north, the Golden State Freeway (I-5) along the northeast, and the Stainless Steel Products Inc. (SSP) facility to the southeast.

The Site has been in the process of re-development for several years. Currently two office buildings, parking and driveways, and landscaping cover Parcel 1, along North Ontario Street. The remainder of Parcel 1 contains parking and driveways for future development and unimproved ground in non-asphalt covered areas. Parcel 3 is covered by asphalt and is currently used as a parking lot. Site development activities have been reinitiated during the Second and Third Quarters of 2006 with building pads and footings being constructed. Construction of two office buildings commenced during the Fourth Quarter 2006 and is continuing through the First Quarter 2007.

The former Weber Aircraft (Weber) Facility was part of an industrialized complex located northeast of the Bob Hope (Burbank) Airport. Weber initially leased the facility from Lockheed Aircraft (Lockheed), and sometime during the early 1960s, purchased the

facility from Lockheed. Prior to Lockheed's ownership, the facility was owned by the Ginsburg Brothers, who operated a distillery at the Site. Weber manufactured aircraft parts and galley assemblies at the Site from the early 1950s until termination of facility operations in 1989. Manufacturing operations conducted by Weber included metal plating, machining, painting, degreasing, and panel assembly work. The facility was decommissioned and demolished in 1992.

2.1 Previous Environmental Activities

Several phases of subsurface investigations have been conducted at the Site since 1988. The investigations consisted of soil gas surveys, soil drilling and sampling and groundwater monitoring. At least 9 soil investigations have been performed between 1988 and 1997, with a focus on investigating areas within the facility where regulated compounds were suspected of being used, around the location of chemical storage areas, in order to delineate releases to soil as identified from earlier investigations, and other areas of environmental concern.

Investigations conducted to date have identified the following chemicals of concern (COC): primarily volatile organic compounds (VOCs), including cis-1,2-dichloroethene (cis-1,2-DCE), 1,1-dichloroethene (1,1-DCE), 1,1,1-trichloroethane (TCA), trichloroethene (TCE) and tetrachloroethene (PCE); aromatic hydrocarbons and total petroleum hydrocarbons (TPH); and metals (cadmium, chromium, copper, nickel, zinc and lead).

Soil gas investigations installed a total of 315 soil probes and analyzed the collected soil gas samples for VOCs. Eleven potentially impacted soil areas (designated ISA1 through ISA11) were identified across the Site. Five of the ISAs (ISA5, 6, 7, 9 and 10) were identified with VOCs in soil samples above a response level of ten times the maximum contaminant level (MCL) or action level for drinking water.

A total of 110 soil borings have been drilled and sampled at the Site to investigate the vertical and lateral extent of contaminants in the subsurface. The majority of samples

that contained detectable concentrations of the COCs were collected from depths of 50 feet below ground surface (bgs) or less. Six samples, collected at 70, 75, 80, 100, and 140 feet bgs contained detectable concentrations of PCE, TCA, and or TCE.

Five groundwater monitoring wells were installed in 1991 and were restored to operational condition in 2004. Historical depths to groundwater beneath the Site ranged between 186.9 feet bgs (measured on January 30, 1996 in well SW-4) to 244.5 feet bgs (measured on December 20, 2004 in well SW-3). The wells have been monitored periodically over the years, but not on a consistent schedule until 2006. Historical groundwater levels are presented in Table 1.

Site remediation activities have consisted of source removal, excavation and removal of VOC and metals-impacted soil, and soil vapor extraction of VOCs. Several areas of shallow soil impacted with VOCs and metals were excavated and the impacted soil removed from the Site. Soil impacted with metals above response levels were excavated from ISA1, ISA2, and ISA4. Shallow soil impacted with metals and VOCs was also removed from ISA7. Source removal included the abandonment of underground storage tanks and demolition of all facility structures on the Site. In conjunction with demolition, limited soil excavation was also performed in 1992.

Vapor wells were installed in five VOC-impacted ISAs from 1991 through 1994 as part of the soil vapor extraction (SVE) system. The SVE system consisted of six vapor extraction wells (V-2 through V-7), four vapor monitoring wells (VM-1 through VM-4) and nine "vapor break" wells (VBW-1 through VBW-9). The vapor extraction wells were screened from 10-30, 50-70, and 80-100 feet bgs. Vapor monitoring wells were installed to monitor soil gas in areas immediately adjacent to, and at some distance from, the extraction wells. Vacuum break wells were installed to monitor the potential for migration of adjacent VOC plumes from the Kahr Bearing and Stainless Steel Products sites toward the SVE system. The SVE system was operated from May 1996 through

January 1997. Soil vapor rebound testing was conducted in October 1997 to document post soil vapor extraction conditions at the Site.

During November 2006 through January 2007, Burns & McDonnell advanced 15 borings ranging in depths from approximately 200 feet bgs to 270 feet bgs. Soil samples were collected at predetermined intervals by the Water Board. Monitoring well SW-4 was decommissioned and replaced by monitoring well MW-4A. Two new groundwater monitoring wells, designated MW-6 and MW-7, were installed to depths of 270 feet bgs. Groundwater samples collected from MW-4A, MW-6 and MW-7 are included in the *First Quarter 2007 Groundwater Monitoring Report*. In addition, 45 soil vapor probes were installed at depths ranging from 35 feet bgs to 200 feet bgs. Details of the additional Site Investigation will be discussed in the forthcoming *Site Investigation Report April 2007*.

3.0 GEOLOGY/HYDROGEOLOGY

3.1 Regional Hydrogeology

The Site is located in the San Fernando groundwater basin. The basin is bounded on the east and north by the San Rafael Hills and Verdugo Mountains, on the north by the San Gabriel Mountains, and on the south by the Santa Monica Mountains. A concrete-lined channel, which originates in the Hanson-La Tuna Canyon area, a tributary to the Los Angeles River, is located approximately 1,100 feet to the southwest. Sediments of Recent and older alluvium underlie the Site, and are composed primarily of sands and gravels derived from igneous and metamorphic rocks eroded from the San Gabriel and Verdugo Mountains.

3.2 Topography and Surface Drainage

The Site is situated on a broad gentle alluvial pediment that slopes generally to the southwest at less than one percent. Regional surface runoff flows to the west and southwest by streets and gutters, storm drains, and some local natural drainage channels.

Site specific surface runoff from Parcel 1 flows to the southeast, discharging through the adjacent property.

3.3 Site Specific Hydrogeology

Based on the drilling and geophysical logs of previous investigations, the Site appears to be underlain by medium dense to dense sand, gravelly sand, and gravels to depths of at least 270 feet bgs. A hard gravel layer is present at a depth of approximately 75 feet bgs, and may represent a zone coincident with the highest groundwater elevation recorded in the area, measured at 72 feet bgs in 1944 (Woodward-Cylde Consultants, 1993, *Drilling at Impacted Soil Areas, Former Weber Aircraft Facility, Burbank, California,: Volume I: August, Final Report*). Other gravel/cobble horizons occur at approximately 140 feet, 160 feet, and 245 to 250 feet bgs. These bedded gravels appear to be laterally discontinuous, and can sometimes be correlated between adjacent borings.

The gravelly sands and cobble horizons typically form interbedded sequences, becoming coarser with increasing depth, and are occasionally separated by laterally extensive or discontinuous rare clays, sandy-silts, silty-sands and silts. The depositional environment for sediments at the Site is a coalescing alluvial fan environment. These observations are consistent with published geologic mapping by the USGS.

3.4 Site Conditions

The following is a brief summary of the groundwater conditions beneath, and in the immediate area of, the Site. Information presented here was summarized from previous reports submitted to the Water Board, and included water elevation and contaminant concentration data from Lockheed wells along San Fernando Boulevard and Ocean Technology, Inc. (OTI), SSP, and Weber wells. The previous reports indicated the following:

• The groundwater gradient in the region surrounding the Site has historically been generally to the south- due to extensive pumping by Lockheed, combined with water extractions from North Hollywood, Mission, and Erwin Well Fields. This

historical pumping created a cone of depression in the area south and west of the Burbank Airport (WCC, 1991).

- The groundwater gradient in the vicinity of the Site is reflective of the regional gradient; with the gradient to the immediate east of the Site sloping to the south-southwest and the gradient beneath the Site sloping to the south (WCC, 1991).
- Possible offsite source areas of COCs detected in Well SW-4 may be located to the north-northeast of Well SW-4 (WCC, 1991).
- Possible offsite source areas of COCs detected in Well SW-5 may be located to the north-northeast of Well SW-4 (WCC, 1991).
- Evaluation of soil and groundwater data from Lockheed, OTI, SSP and Weber files indicated the presence of significant releases of PCE and TCE from upgradient facilities, not inclusive of the Site (WCC, 1991).
- The PCE plume is centered on the location of the former SSP solvent landfarming area and is elongated in a north-south direction (WCC, 1991). Soil borehole sample data collected by SSP confirmed PCE in soil at depth at concentrations of 13,000 micrograms per kilograms (μg/Kg) beneath the former landfarm area (A.L. Burke Engineers, Inc. 1989. Phase III Site Investigation Stainless Steel Products Corporation Burbank, California, August 1989).
- The area wide TCE plume is centered on OTI and is elongated in a north-south direction, WCC, 1991).

4.0 GROUNDWATER SAMPLING ACTIVITIES

The quarterly groundwater monitoring and well sampling program was reinitiated in January 2006. Monitoring well SW-4 was decommissioned and replaced by monitoring well MW-4A. Two new groundwater monitoring wells, designated MW-6 and MW-7, were installed to depths of 270 feet bgs.

4.1 Well Gauging Procedures

On February 20, 2007, static groundwater level measurements were obtained at 7 monitoring wells (SW-1, SW-2, SW-3, MW-4A, SW-5, MW-6 and MW-7). Prior to obtaining groundwater level measurements, the well caps from each wellhead were removed in order for the water levels to reach static equilibrium. For each well, the depth to groundwater was measured from a surveyed reference point at the top of the well casing using an electronic interface probe. Measurements were recorded to the nearest 0.01 feet. Prior to measuring groundwater levels in the monitoring wells, the measuring tape of the interface probe was washed in an Alconox/water solution and rinsed with deionized water. Groundwater level measurements were recorded on the Groundwater Sampling Forms, which are provided in Appendix A.

4.2 Well Purging Procedures

Prior to groundwater purging, the volume of water inside monitoring wells SW-1, SW-2 SW-3 and SW-5 was calculated using the groundwater level measurements and measured well depths. For purging procedures at Wells MW-4A, MW-6 and MW-7, see *Section 4.5 Well Development and Sampling*. The monitoring wells were purged using a 3-inch submersible pump operated by BC² Environmental Corporation. During purging, water quality parameters (including pH, electrical conductivity, turbidity, dissolved oxygen and temperature) were monitored and recorded on the Groundwater Sampling Forms (Appendix A). Water quality parameters were measured until a minimum of three well volumes were removed. Once the well volumes were purged and the water quality parameters had stabilized to within plus or minus 10 percent, samples were collected. The data was recorded on the Groundwater Sampling Forms.

4.3 Purge Water Disposal

Purged groundwater was collected in a 300-gallon tank and transferred into 55-gallon drums, which were then labeled, sealed, and stored onsite (in the northeast corner of the Site, near Well SVP-1) to await transportation and disposal at an appropriate facility.

4.4 Groundwater Sampling

Groundwater samples were collected at SW-1, SW-2, SW-3 and SW-5 using disposable polyethylene bailers and a representative aliquot was then dispensed into laboratory-supplied sample containers. The sample containers were labeled and placed on crushed ice inside an insulated ice chest for transport to the analytical laboratory. Chain-of-Custody documentation was prepared and accompanied the samples to the analytical laboratory.

Field measurements and observations noted during sampling were recorded on the Groundwater Sampling Forms (Appendix A).

4.5 Well Development & Sampling

On February 20th and 21st, newly installed groundwater monitoring Wells MW-6, MW-7 and MW-4A were developed and sampled by Blaine Tech Services Inc. Wells MW-6 and MW-7 were developed using a 2-inch submersible pump attached to new, disposable polyethylene tubing. The pump was set at the bottom of each well casing. Both wells are slightly bent at approximately 210-220 feet bgs. Standard surge and bail techniques were not possible at these locations. Well MW-4A was developed with a combination of a Waterra Power Pump and a peristaltic pump. Well MW-4A is also slightly bent at approximately 210-220 feet bgs. A Myron Ultrameter L was employed to measure groundwater parameters (pH, electrical conductivity, turbidity and temperature). Wells were continuously purged until a minimum of 10 casing volumes had been removed and field parameters had stabilized to within +/- 10 percent. Well development water was collected in the development vehicle storage tank and then transferred into 55-gallon drums, which were then labeled, sealed, and stored onsite (in the northeast corner of the Site, near Well SVP-1) to await transportation and disposal at an appropriate facility.

Wells MW-6, MW-7 and MW-4A were sampled after field parameters had stabilized to within +/- 10 percent. Samples were submitted under Chain-of-Custody documentation to the analytical laboratory. The Well Development / Well Monitoring forms are included in Appendix A.

4.6 Quality Control Sampling

A rinsate sample, designated Rinsate-1, was collected as a quality assurance / quality control sample (QA/QC). The rinsate sample was obtained after sampling and decontaminating at Well MW-6, and prior to purging and sampling at Well MW-7. The rinsate sample was submitted for analysis of dioxins/furans (Method DLM02.0). Trip blanks accompanied groundwater samples on each day of the sampling event. Trip blanks were analyzed for VOCs and 1,2,3-Trichloropropane (1,2,3-TCP).

5.0 GROUNDWATER FLOW CONDITIONS

Wells SW-1 through SW-5 were resurveyed on March 21, 2006; newly installed groundwater monitoring wells MW-4A, MW-6 and MW-7 were surveyed on March 2, 2007 for easting, northing and elevation. These two data sets were utilized in evaluating groundwater flow conditions for this monitoring event. Groundwater level measurement data was used to assess the flow direction and gradient for the monitoring wells, screened from 190 feet bgs to 272 feet bgs at the Site. Groundwater elevation data is presented in Table 1. Groundwater elevation contours (as measured on February 20, 2007), flow direction and gradient are presented on Figure 2.

During the February monitoring event, the depth to groundwater ranged between 218.49 feet to 226.76 feet below the top of casing (TOC). Groundwater elevations ranged from 472.28 feet (SW-5) as referenced to mean sea level (msl) to 485.04 feet (SW-1, offsite and upgradient) msl, showing a difference in elevation of 12.76 feet across the Site.

Groundwater flow direction during this event continued to be toward the south, at an average gradient of 0.006 feet per foot (ft/ft).

6.0 ANALYTICAL RESULTS

The following discussion of analytical results focuses on those constituents which were detected at concentrations in excess of the laboratory reporting limits and had no quality control qualifiers flagged by the analytical laboratory. In order to see those results that had a qualifier flagged by the analytical laboratory, see the corresponding tables in this report, the Certified Laboratory Reports presented in Appendix B, and Burns & McDonnell's QA/QC Review of Analytical Data presented in Appendix C.

The following list of analyses was requested on groundwater samples collected for this sampling event:

- VOCs (EPA 8260B)
- 1,4-Dioxane (EPA 8270C)
- Title 22/CAM 17 Metals (EPA 6010B/7470A)
- Hexavalent Chromium (EPA 7199)
- Anions (NO₂, NO₃, SO₄, Cl) (EPA 300.0)
- Perchlorate (EPA 314.0)
- Dissolved Oxygen (EPA 360.1)
- Sulfide (EPA 9034)
- 1, 2, 3-Trichloropropane (EPA 524 SIM)
- N-Nitrosodimethylamine (NDMA) (EPA 1625C-CI Mod)
- Cations (EPA 6010)
- Dissolved Iron & Manganese (EPA 6010B-Diss)
- Dioxins/Furans (Method DLM02.0)

6.1 Title 22 Metals

Seven groundwater samples were analyzed for Title 22/CAM 17 Metals (6010B/7470A) during the January / February 2007 sampling event. Analytical results are presented in Table 2; Certified Analytical Reports and Chains of Custody documentation are presented in Appendix B. The following is a listing of the metals results:

TABLES

TABLE 1 CUMULATIVE GROUNDWATER ELEVATIONS DATA Former Weber Aircraft Facility Burbank, California

Well Identification	Date of Measurement	Screened ³ Interval (ft. bgs)	Blank Casing Interval	Depth to Water Below TOC (ft.)	Top of Casing Elevation (ft.msl) ¹	Ground Surface ⁵ Elevation (ft.msl) ²	Groundwate Elevation (ft.msl) ²
SW-2	3/19/91	190-245 190-245	220-225 220-225	224.05 223.70	702.49 702.49	702.43 702.43	478.44
	4/15/91 5/10/91	190-245	220-225	223.70	702.49 702.49	702.43	478.79 478.54
	6/14/91	190-245	220-225	224.40	702.49	702.43	478.09
	7/15/91	190-245	220-225	224.86	702.49	702.43	477.63
	8/15/91 9/17/91	190-245 190-245	220-225 220-225	225.45 225.88	702.49 702.49	702.43 702.43	477.04 476.61
	11/18/91	190-245	220-225	227.02	702.49	702.43	475.47
	12/12/91	190-245	220-225	227.60	702.49	702.43	474.89
	1/17/92	190-245	220-225	227.57	702.49	702.43	474.92
	4/14/92 5/15/92	190-245 190-245	220-225 220-225	228.3 4 228.27	702.49 702.49	702.43 702.43	474.15 474.22
	6/16/92	190-245	220-225	228.52	702.49	702.43	473.97
	7/8/92	190-245	220-225	228.86	702.49	702.43	473.63
	8/19/92	190-245	220-225	228.43	702.49	702.43	474.06
	9/17/92	190-245	220-225	228.63	702.49	702.43	473.86
	10/27/92 11/19/92	190-245 190-245	220-225 220-225	229.10 229.01	702.49 702.49	702.43 702.43	473.39 473.48
	12/18/92	190-245	220-225	228.78	702.49	702.43	473.71
	1/15/93	190-245	220-225	228.75	702.49	702.43	473.74
	2/19/93	190-245	220-225	228.02	702.49	702.43	474.47
	3/10/93 4/14/93	190-245 190-245	220-225 220-225	227.86 226.80	702.49 702.49	702.43 702.43	474.63 475.69
	5/18/93	190-245	220-225	225.31	702.49	702.43	477.18
	6/15/93	190-245	220-225	223.70	702.49	702.43	478.79
	7/14/93	190-245	220-225	222.04	702.49	702.43	480.45
	8/24/93	190-245	220-225	219.44	702.49	702.43	483.05
	9/14/93	190-245	220-225	218.74	702.49 702.49	702.43	483.75
	10/25/93 11/15/93	190-245 190-245	220-225 220-225	216.74 215.89	702.49 702.49	702.43 702.43	485.75 486.60
	12/20/93	190-245	220-225	213.95	702.49	702.43	488.54
	1/8/94	190-245	220-225	212.68	702.49	702.43	489.81
	2/27/94	190-245	220-225	210.48	702.49	702.43	492.01
	3/16/94	190-245	220-225	209.57	702.49	702.43	492.92
	4/27/94 5/19/94	190-245 190-245	220-225 220-225	208.02 207.18	702.49 702.49	702.43 702.43	494.47 495.31
	6/16/94	190-245	220-225	205.96	702.49	702.43	496.53
	7/20/94	190-245	220-225	204.85	702.49	702.43	497.64
	8/30/94	190-245	220-225	204.03	702.49	702.43	498.46
	9/15/94	190-245 190-245	220-225	203.60	702.49	702.43	498.89
	10/17/94 11/14/94	190-245	220-225 220-225	203.82 204.02	702.49 702.49	702.43 702.43	498.67 498.47
	12/21/94	190-245	220-225	204.27	702.49	702.43	498.22
	1/26/95	190-245	220-225	204.65	702.49	702.43	497.84
	2/23/95	190-245	220-225	204.89	702.49	702.43	497.60
	4/19/95	190-245	220-225 220-225	205.24	702.49 702.49	702.43	497.25
	5/11/95 6/17/95	190-245 190-245	220-225	205.30 204.85	702.49 702.49	702.43 702.43	497.19 497.64
	7/10/95	190-245	220-225	204.29	702.49	702.43	498.20
	8/24/95	190-245	220-225	203.11	702.49	702.43	499.38
	9/12/95	190-245	220-225	203.25	702.49	702.43	499.24
	10/11/95 11/17/95	190-245 190-245	220-225 220-225	202.69 201.95	702.49 702.49	702.43 702.43	499.80
	1/3/96	190-245	220-225	200.90	702.49	702.43	500.54 501.59
	1/29/96	190-245	220-225	200.48	702.49	702.43	502.01
	2/22/96	190-245	220-225	200.72	702.49	702.43	501.77
	4/23/96	190-245	220-225	200.51	702.49	702.43	501.98
	5/22/96 6/18/96	190-245 190-245	220-225 220-225	200.86 201.33	702.49 702.49	702.43 702.43	501.63 501.16
	7/21/96	190-245	220-225	202.09	702.49	702.43	500.40
	8/18/96	190-245	220-225	202.80	702.49	702.43	499.69
	9/25/96	190-245	220-225	203.67	702.49	702.43	498.82
	10/25/96 1/26/96	190-245 190-245	220-225 220-225	204.27 204.83	702.49 702.49	702.43 702.43	498.22 497.66
	12/29/96	190-245	220-225	205.76	702.49	702.43	496.73
	1/30/97	190-245	220-225	206.70	702.49	702.43	495.79
	2/25/97	190-245	220-225	207.27	702.49	702.43	495.22
	3/31/97	190-245	220-225	208.15	702.49	702.43	494.34
	4/24/97 5/30/97	190-245 190-245	220-225 220-225	208.47 209.67	702.49 702.49	702.43 702.43	494.02 492.82
	6/24/97	190-245	220-225	210.53	702.49	702.43	491.96
	6/15/97	190-245	220-225	211.24	702.49	702.43	491.25
	8/29/97	190-245	220-225	213.11	702.49	702.43	489.38
	9/26/97	190-245	220-225	214.46	702.49	702.43	488.03
	10/23/97 11/11/97	190-245 190-245	220-225 220-225	215.25 207.41	702.49 702.49	702.43 702.43	487.24 495.08
	10/12/97	190-245	220-225	208.57	702.49	702.43	493.92
	1/28/98	190-245	220-225	208.59	702.49	702.43	493.90
	2/3/98	190-245	220-225	208.18	702.49	702.43	494.31
	4/28/98 5/20/08	190-245	220-225	208.28	702.49	702.43	494.21
	5/29/98 6/12/98	190-245 190-245	220-225 220-225	207.96 207.65	702.49 702.49	702.43 702.43	494.53 494.84
	7/30/98	190-245	220-225	206.43	702.49	702.43	496.06
	9/4/98	190-245	220-225	205.97	702.49	702.43	496.52
	10/9/98	190-245	220-225	205.02	702.49	702.43	497.47
	11/25/98	190-245	220-225	205.10	702.49 702.40	702.43	497.39
	10/21/98 1/20/99	190-245 190-245	220-225 220-225	203.72 203.14	702.49 702.49	702.43 702.43	498.77 499.35
	2/11/99	190-245	220-225	203.14	702.49 702.49	702.43 702.43	499.35 497.80
	3/12/99	190-245	220-225	203.59	702.49	702.43	498.90
	4/8/99	190-245	220-225	204.19	702.49	702.43	498.30
	5/20/99	190-245	220-225	204.37	702.49	702.43	498.12
	6/10/99 7/27/99	190-245 190-245	220-225 220-225	204.35 208.00	702.49 702.49	702.43 702.43	498.14
	7/27/99 8/17/99	190-245 190-245	220-225	208.00	702.49 702.49	702.43 702.43	494.49 497.34
	9/16/99	190-245	220-225	210.79	702.49	702.43	491.70
	10/15/99	190-245	220-225	212.10	702.49	702.43	490.39
	11/12/99	190-245	220-225	215.00	702.49	702.43	487.49
	12/10/99	190-245	220-225	215.69	702.49	702.43	486.80
	1/27/00 12/20/02	190-245 190-245	220-225 220-225	217.98 229.88	702.49 702.49	702.43 702.43	484.51 472.61
	12/20/02	190-245	220-225	240.00	702.49	702.43	462.49
					702.14	702.40	474.68
	1/12/06	190-245	220-225	. 227.40		702.40	.,
	4/26/06	190-245	220-225	224.15	702.14	702.40	477.99
	4/26/06 7/18/06	190-245 190-245	220-225 220-225	224.15 222.05	702.14 702.14	702.40 702.40	477.99 480.09
	4/26/06	190-245	220-225	224.15	702.14	702.40	477.99

TABLE 2 SUMMARY OF

Title 22/CAM 17 Metals, Hexavalent Chromium, Dissolved Metals and Mercury

First Quarter 2007 Former Weber Aircraft Facility Burbank, California

										Titl	e 22/CAM	17 Metals	(6010 B)										60	10B	7470A
Well ID	Date Sampled	Ag	As	Ва	Be	Ca	Cd	Co	Cr	Cr 6* (7199)	Cu	K	Mg	Мо	Na	Ni	Pb	Sb	Se	п	v	Zn	Fe dissolved	Mn dissolved	Hg
Analytical Re	eporting Units	µg/L	µg/L	μg/L	µg/L	μg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	µg/L	μg/L	μg/Ľ	µg/L	µg/L	μg/L	μg/L	μg/L	µg/L	μg/L	μg/L
California N	MCLs (µg/L)	100	50	1,000	4	No MCL	5	730***	50	50	1,300**	No MCL	No MCL	180***	No MCL	100	15*	6	50	2	36***	5,000	300	50	2
SW-1	21-Dec-04	NA	NA	NA	NA	NA	NA	NA	3****	1.4****	4****	NA	NA	NA	NA	5****	<5****	NA	NA	NA	NA	114****	NA	NA	NA
	12-Jan-06	<10	<10	85	U	62,500	<5.0	<50	96	5.2	<25	3,000 B	15,600	17 B	99,300	8.7 B	3.1 B	<60	<5.0	<10	12 B	33	<100	4.2 B	<0.2
	26-Apr-06	<1.0	1.4 J	143 J	0.13 B,J	68,000 J	<1.0	8.5 J	174	5.9	33.8 J	2,890	16,300 J	8.9	92,400 J	67.0	57.1 J	<2.0	1.1 J	<1.0	30.5	206 J	<50	2.7	<0.2
	18-Jul-06	<10	9.9	200	<4.0	66,000	<5.0	13	1,600	5.5	72	5,800	20,000	37	100,000	140	55	<10	11	<10	67	280	- <40	<20	<0.2
	17-Oct-06	<10	<10	85	<4.0	60,000	<5.0	<10	23	4.9	<10	2,800	15,000	<20	92,000	12	7.3	<10	<10	<10	16	13	<40	<20	<0.2
	17-Jan-07	<10	<10	100	<4.0	66,000	<5.0	<10	220	4.9	20	3,300	17,000	<20	100,000	25	20	<10	<10	<10	. 21	1,400	<40	20	<0.2
SW-2	20-Dec-04	NA	NA	NA	NA	NA	NA	NA	9****	6.7****	4****	NA	NA	NA	NA	4****	<5****	NA	NA	NA	NA	93****	NA	NA	NA
	12-Jan-06	<10	9.8 B	88	U	67,500	<5.0	<50	14	12	<25	4,100 B	21,800	11 B	59,500	<40	<5.0	< 0.060	<5.0	<10	8.4 B	11 B	<100	9.5 B	<0.2
	26-Арт-06	<1.0	1.1 J	88 J	<1.0	58,700 J	<1.0	1.0 J	26.5	12	3.4 J	4,320	22400 J	11.6	63000 J	6.2	6.9 J	0.23 B,J	1.1 J	<1.0	9.3	298 J	<50	7.6	<0.2
	19-Jul-06	<10	<5.0	96	<4.0	63,000	<5.0	<10	26	8.8	<10	4,700	22,000	<20	74,000	<10	5.8	<10	<10	<10	13	180	<40	<20	<0.2
	17-Oct-06	<10	<10	91	<4.0	63,000	<5.0	<10	14	10	<10	4,000	21,000	<20	60,000	<10	<5.0	<10	<10	<10	<10	49	<40	<20	<0.2
	17-Jan-07	<10	<10	220	<4.0	84,000	<5.0	15	130	10	35	7,200	30,000	<20	67,000	52	37	<10	<10	<10	42	260	<40	<20	<0.2
SW-3	21-Dec-04	NA	NA	NA	NA	NA	NA	NA	<10****	0.4****	4****	NA	NA	NA	NA	43****	<5****	NA	NA	NA	NA	86****	NA	NA	NA
	13-Jan-06	<10	<10	120	U	87,600	<5.0	<50	78	80	<25	5,000	30,200	9.5 B	63,600	9.2 B	<5.0	<60	<5.0	<10	4.2 B	21	U*	7.2 B	<0.2
	26-Apr-06	<1.0	1.7 J	160 J	<1.0	87,100 J	<1.0	5.8 J	663	210	18.4 J	5,260	30,600 J	12.1	58,700 J	110	3.7 J	0.30 B,J	1.0 J	<1.0	8.0	419 J	28.0 B	23.3	<0.2
	18-Jul-06	<10	<5.0	140	<4.0	85,000	<5.0	<10	770	580	18	6,200	33,000	<20	56,000	62	6.6	<10	<10	<10	12	2,200	<40	27	<0.2
	17-Oct-06	<10	<10	140	<4.0	85,000	<5.0	<10	300	250	11	4,900	31,000	<20	49,000	48	<5.0	19	<10	<10	12	220	<40	<20	<0.2
	17-Jan-07	<10	<10	140	<4.0	87,000	<5.0	<10	640	210	13	5,700	33,000	<20	50,000	49	10	<10	<10	<10	12	1,100	<40	20	<0.2
SW-4¹	21-Dec-04	NA	NA	NA	NA	NA	NA	NA	6****	2.2****	5****	NA	NA	NA	NA	9****	<5****	NA	NA	NA	NA	75****	NA	NA	NA
	13-Jan-06	<10	<10	110	U	75,400	<5.0	<50	33	13	5.5 B	3,700 B	22,600	7.0 B	38,800	14 B	8.8	<60	<5.0	<10	9.5 B	99	<100	2.9 B	<0.2
	27-Apr-06	<1.0	1.1 J	140 J	<1.0	82,900 J	0.24 B	3.1 J	88.7	50	10.0 J	4,200	26,400 J	6.5	41,800 J	22.7	13.3 J	0.46 B,J	1.2 J	<1.0	11.1	346 J	25.0 B	4.2	NR
ļ	19-Jul-06	<10	<5.0	120	<4.0	68,000	<5.0	<10	250	40	36	11,000	30,000	<20	59,000	79	28	<10	<10	<10	19	1,900	<40	<20	<0.2
	18-Oct-06	<10	<10	140	<4.0	91,000	<5.0	<10	100	240	<10	4,800	33,000	<20	52,000	54	<5.0	<10	<10	<10	<10	190	<40	<20	<0.2
MW-4A¹	21-Feb-07	<10	<10	57	<4.0	88,000 B-1	<5.0	<10	8.4	5.7	<10	4,700	26,000	<20	49,000	<10	<5.0	<10	<10	<10	<10	<20	<40	56	<0.2
SW-5	20-Dec-04	NA	NA	NA	NA	NA	NA	NA	11****	9.6****	3****	NA	NA	NA	NA	70****	4****	NA	NA	NA	NA	96****	NA	NA	NA
l	13-Jan-06	<10	<10	140	U	88,500	<5.0	<50	7.6 B	4.6	<25	4,800 B	30,700	8.7 B	53,100	22 B	<5.0	<60	<5.0	<10	4.4 B	87	<100	17	<0.2
	27-Apr-06	<1.0	1.8 J	178 J	<1.0	94,100 J	<1.0	6.1 J	498	7.4	17.6 J	5,270	33,000 J	10.2	54,800 J	79.1	6.7 J	0.24 B,J	1.0 J	<1.0	9.0	386 J	<50.0	22.2	<0.2
ļ	19-Jul-06	<10	6.2	120	<4.0	82,000	<5.0	<10	100	22	<10	5,700	33,000	<20	52,000	16	5.4	<10	<10	<10	<10	1,200	<40	<20	<0.2
į	18-Oct-06	<10	<10	140	<4.0	92,000	<5.0	<10	12	12	<10	4,800	34,000	<20	52,000	33	<5.0	<10	<10	. <10	<10	64	<40	23	<0.2
	17-Јал-07	<10	<10	170	<4.0	98,000	<5.0	<10	350	13	12	5,700	34,000	<20	54,000	50	8.2	<10	<10	<10	15	1,600	<40	69	<0.2
MW-6 ²	20-Feb-07	<10	<10	31	<4.0	66,000	<5.0	<10	<5.0	3.6	<10	4,800	20,000	<20	50,000	<10	<5	<10	<10	<10	<10	<20	<40	140	<0.2
MW-7 ³	21-Feb-07	<10	<10	48	<4.0	91,000	<5.0	<10	5.1	<2.0	<10	6,300	32,000	<20	58,000	<10	<5	<10	<10	<10	· <10	<20	<40	180	<0.2

Motes:	
Bold	Results in excess of MCL are in bold. Analyses for the current quarter are italicized.
1 =	MW-4A installed January 7, 2007. SW-4 Decommissioned January 2007.
2 =	MW-6 installed December 2007
3 =	MW-7 installed December 2007
NR =	Not reported.
M =	"CAL-Modified PRG"
NL =	Not listed.
NA =	Not analyzed.
NS ≖	Not sampled

MELITOUS A	ind MCLS.
(7199)	Analytical Method 7199
* =	The lead action level is exceeded if the concentration of lead in more than 10 percent of tap water samples
	collected during any monitoring period conducted in accordance wi Article 6 is greater than 15 ug/L.
** =	The copper action level is exceeded if the concentration of copper in more than 10 percent of tap water samples
	collected during any monitoring period conducted in accordance wi Article 6 is greater than 13 ug/L.
*** =	No MCL listed, California Region 9 PRG (October 2004) value for tap water is reported.
****	Test number 200.7 used for detection in 2004 Laboratory results.
*****	Test number 218 6 used for detection in 2004 Laboratory results

aboratory Qualifiers

- B-1 = Analyte was detected in the associated method blank. Analyte concentration in the sample is greater than 10x the concentration found in the method blank.
- $B \approx$ Estimated result. Result is less than reporting limit.
- U = False positive and qualified as undetected due to blank contamination.
- J = Estimated result. Samples run outside of 8-hour holding time.

TABLE

SUMMARY OF INORGANIC COMPOUNDS

1,4-Dioxane, NDMA, PERCHLORATE, SULFATE and CHLORIDE

First Quarter 2007

Former Weber Aircraft facility Burbank, California

		360.1			300.0A			314.0	9030B/9034	8270 C (SIM)	1625 M
		Dissolved Oxygen	Chloride	Nitrite as (N)	Nitrate as (N)	Nitrate as (NO3)*	Sulfate	Perchlorate	Sulfides (total)	1,4 - Dioxane	NDMA
Well ID	Date Sampled	μg/L	μg/L	μg/L	μg/L	μg/L	μg/L	µg/L	μg/L	µg/L	μg/L
California MCL (µg/L)		No MCL	250,000	1,000.0	10,000 (USEPA)	_ 45,000	250,000	3.6 µg/L	No MCL	6.1 µg/L	0.0013 μg/L
SW-1	21 Dec 04	NA	NA	NA	NA	NA	NA	<4.0	NA	<2	NA
	12-Jan-06	8,100	49,100	<500 G	8,000	35,432	77,800	2.9 B	<4,000	<0.95	<0.002
	26-Apr-06	8,400 J	54,100	<100	8,300	36,761	85,700	2.7 B	<4,000	<1.0	<0.002
	18-Jul-06	4,800 J	52,000	<750 RL-1	7,800	34,546	80,000	<4.0	<1,000	< 0.47	<0.0020
	17-Oct-06	5,000	51,000	<150	8,400	37,204	76,000	<4.0	<1,000	<0.50	<0.0020
	17-Jan-07	4,400	51,000	<150	8,500	37,647	77,000	<4.0	<1,000	2.9	<0.0020
SW-2	20-Dec-04	NA	NA	NA	NA	NA	NA	<4.0	NA	<2	NA
	12-Jan-06	6,900	43,800	<500 G	8,400	37,204	75,700	2.6 B	3,400 B	<0.95	<0.002
	26-Apr-06	7,400 J	40,300	<1,000	9,000	39,861	73,500	2.5 B	<4,000	<0.96	<0.002
	19-Jul-06	5,200 J	42,000	<150	7,000	31,003	74,000	<4.0	<1,000	<0.48	0.0028
	17-Oct-06	4,600	43,000	<150	8,100	35,875	78,000	<4.0	<1,000	<0.48	<0.0019
	17-Jan-07	4,700	44,000	<150	7,400	32,775	76,000	<4.0	<1,000	<0.47	<0.0019
SW-3	21-Dec-04	NA	NA	NA	NA	NA	NA	236	NA	<2	NA
•	13-Jan-06	7,400	52,500	<500 G	11,000	48,719	81,000	2.3 B	<4,000	6.8	<0.002
	26-Apr-06	7,500	50,600	<100	10,800	47,833	83,800	4.1	<4,000	<1.0	<0.002
	18 - Jul-06	5,100 J	45,000	<150	12,000	53,148	86,000	<4.0	<1,000	0.5	<0.0019
	17-Oct-06	5,100	45,000	<150	15,000	66,435	81,000	<4.0	<1,000	0.58	<0.0019
	17-Jan-07	5,600	49,000	<150	13,000	57,577	81,000	<4.0	<1,000	0.71	<0.0019
SW-4 ²	21-Dec-04	NA	NA	NA	NA	NA	NA	<4.0	NA	14	NA
	13-Jan-06	6,700	43,000	<500 G	8,600	38,089	79,100	<4.0	<4,000	<0.95	<0.002
	27-Apr-06	7,000	37,600	<100	16,600	73,521	68,700	2.0 B	<4,000	110	<0.002
	19-Jul-06	3,300 J	35,000	<150	16,000	70,864	58,000	<4.0	<1,000	150	<0.0019
	18-Oct-06	4,600	32,000	<750	20,000	88,580	62,000	<4.0	<1,000	350	<0.0019
MW-4A ¹	21-Feb-07	4,300 HFT	55,000	<150	9,300	41,190	110,000	<4.0	<1,000	<0.5	<0.0020 A-01
SW-5	20-Dec-04	NA	NA	NA	NA	NA	NA	<4.0	NA	3.2	NA
	13-Jan-06	7,500	47,400	<500 G	9,700	42,961	89,600	<4.0	<4,000	<0.95	<0.002
	27-Apr-06	9,400 J	50,300	<100	10,100	44,733	95,400	<4.0	<4,000	4.7	<0.002
	19-Jul-06	3,600]	46,000	<150	9,400	41,633	86,000	<4.0	<1,000	27	<0.0019
	18-Oct-06	4,900	32,000	<150	20,000	88,580	62,000	<4.0	<1,000	290	<0.0019
	17-Jan-07	5,400	49,000	<150	11,000	48,719	89,000	<4.0	<1,000	650 Z 3	<0.0019
MW-6 ³	20-Feb-07	3,700	42,000	160	7,300	32,332	87,000	<4.0	<1,000	<0.51 RL4	<0.0020
MW-74	21-Feb-07	3,700 HFT	53,000	<150	8,000	35,432	82,000	<4.0	<1,000	<0.5	0.0022

Notes

Results in excess of MCL are in bold. Analyses for the current quarter are italicized.

B = Estimated result. Result is less than reporting limit.

G = Elevated reporting limit. The reporting limit is elevated due to matrix interference.

NS = Not sampled

NL = Not listed

NA = Not analyzed

NDMA = N-Nitrosodimethylamine

*= Nitrate as NO3 Converted from Nitrate as (N). (Nitrate as (N) μg/L) x 4.429 = Nitrate as NO3 μg/L

I = MW-4A installed January 7, 2007

2= SW-4 Decomissioned January 2007

3 = MW-6 installed December 2007

4 = MW-7 installed December 2007

Laboratory Qualifiers:

HFT = The holding time for tis test is immediate. It was analyzed in the laboratory as soon as possible after reciept.

A-01 = Batch had acceptable BS recoveries. Internal Standard for BSD was most likley double-spiked

which made NDMA recovery appear to be low. BSD recovery seemed to be isolated incident

and should not affect sample results.

RL-1 = reporting limit raised due to sample matrix effects

RL-4 = Reporting limit raised due to insufficient sample volume.

Z3 = The sample required a dilultion due to the nature of the sample matrix.

Because of this dilution, the surrogate spike concentration in the sample was reduced to a level useful information.

where the recovery calculation dose not provide useful information

J = Estimated result. Samples run outside of 8-hour holding time.

Table 4 Dioxin/Furans First Quarter 2007 Former Weber Aircraft Facility Burbank, California

Well 1D	Sample	2.3.7.8.m.		2.3.7.8.1°C	\$ /	1,23,7,8,P.		123,78	, 40,34m	434.5	A A COP	12342	OO HANDO	1,236,78,1		1,2,3,7,8,9,4,	- Copy	123478	40,44	1236.5	W. Sett. COF	\frac{1}{2}	ACOMPORT	, / ;	AG ZAHACOF	12346.	and the state of t	12396.	ACOHRODE		WASTLY .	\\ \delta	; ; 	\$	<i>\$</i>	,		, QJ	A TO THE	É	TAL PROD	É	TALPODE		TOWH THE CO.		POTAL HACOF		POTAL PROCES	\$\frac{\text{Q}}{2}	POTAL H.		Total 2,3,7,8,7,0,2
SW-3	17-Jan-07	1.02	U	1.03	ב ע	1.23	נ ע	2.23	U	2.12	U	2.29	U	3.02	U 3	.19	U 0.	.825	U	0.742	U	0.881	U	0.872	U	2.24	U	1.49	U	1.89	U	4.41	ט	4.08	U	1.02	U	1.03	U	2.23	U	2.23	U	3.19	י ט	0.9	5 U	2.2	4 I	U 1	1.89	U	0.000
MW-4A	21-Feb-07	1.28	U	1.38 U	ט 1	.31	נונ	2.39	U	2.16	บ	2.04	U	2.55	บ 2	.73	บ 1	.06	U	0.88	U	1.06	U	0.996	U	2.34	U	1.54	U	2.08	υ	5.29	ט	4.84	υ	1.28	U	1.38	U	1.31	U	2.39	υ	2.73	3 U	1.00	<u>ں</u>	2.34	4 t	U 2	2.08	U	0.000
SW-5	17-Jan-07	1.02	U	1.04	IJ 2	.75	נוני	2.37	υ	2.36	U	2.32	U	3.04	U 3	.39	U 1	53	U	1.46	U	1.88	υ	1.68	U	9.38	J	1.91	υ	2.5	υ	53.1		4.1	U	1.02	U	1.04	U	2.75	υ	2.44	υ	3.39	, U	1.9	U	19.4	4 J] :	2.5	U	0.147
MW-6	20-Feb-07	1.5.2	יוש	0.901 T	J 1	.46	J 1	.31	U	1.18	U	2.51	υ	3.31	U 3	.52	U 1	.12	U	0.997	U	1.4	U	1.26	U	2.47	U	2.28	U	2.86	υ	3.09	U	4.61	บ	1.52	U	0.901	U	1.46	U	1.31	U	3.52	2 U	1.4	ט	2.47	7 t	<u>ل</u> 2	2.86	U	0.000
MW-7	21-Feb-07	1.55	U	1.18 U	IJ 1	.26	J 2	2.12	U	1.96	U	2.36	U	2.97	U 1	.45	U 1	.24	U	1.12	U	1.45	U	1.34	υ	2.78	U	1.44	U	1.89	U	3.11	U	5.12	U	1.55	U	1.18	U	1.26	U	2.12	υ	3.21	נו	1.4!	i U	2,71	3 t	U 1	89	U	0.000
linsate-1	21-Feb-07	1.53	บ	0.977 T	J 1	.65	J 2	2.59	U	2,22	U	3.32	U	4.05	U 4	.34	U 0.	969	U	0.938	υ	1.25	U	1.13	U	2.56	U	1.41	υ	1.66	U	4.81	U	5.02	U	1.53	υ	0.977	U	1.65	U	2.59	U	4.34	ט	1.2	; U	2.50	5 l	U 1	.66	U	0.000

All sample results in picograms per gram (pg/L)

bgs - below ground surface

Total 2,3,7,8-TCDD equivalent calculated by multiplying the toxicity equivalency factor by the detected concentration.

Toxicity Equivalency Factors represent the WHO/98 values from Table 9-2 of USEPA's December 2003 $\,$

NAS Review Draft Exposure and Human Health Reassessment of 2,3,7,8-Tetrachlorodibenzo-p-Dioxin (TCDD)

and Related Compounds (NCEA-I-0836).

Qualifiers:

U = Result below detection limit

J = Analyte concentration is below calibration range

California MCL for TCCD Equivalent

30 ng/T.

TABLE 5 SUMMARY OF VOLATILE ORGANIC COMPOUNDS First Quarter 2007

Former Weber Aircraft Facility Burbank, California

21-Dec-04 12-Jan-06 26-Apr-06 18-Jul-06 17-Oct-06 17-Jan-07	μg/L 5 <5 <0.1 <1.0 <1.0 <1.0 <1.0	μg/L 5 <5 <1.0 0.74 J <1.0 <1.0 <1.0	μg/L 200 <5 <1.0 <1.0 <1.0 <1.0	μg/L 5 NA <1.0 <1.0 <1.0	μg/L 5 NA <1.0 <1.0	µg/L 0.5 NA <1.0	µg/L 6 <5	µg/L 6	μg/L 10	µg/Ł	µg/L	µg/L	μg/L	µg/L	µg/L	μg/L	µg/L	µg/L	h8/L	µg/L	μg/L	µg/L
21-Dec-04 12-Jan-06 26-Apr-06 18-Jul-06 17-Oct-06 17-Jan-07 20-Dec-04	<5 <0.1 <1.0 <1.0 <1.0	<1.0 0.74 J <1.0 <1.0	<5 <1.0 <1.0 <1.0	<1.0 <1.0	<1.0	NA NA	6 <5	6	10			F-										
12-Jan-06 26-Apr-06 18-Jul-06 17-Oct-06 17-Jan-07 20-Dec-04	<0.1 <1.0 <1.0 <1.0	<1.0 0.74 J <1.0 <1.0	<1.0 <1.0 <1.0	<1.0 <1.0	<1.0		<5			0.0012	0.0056**	0.5	0.17**	4.3**	110**	0.13**	0.18**	1.0	150	300	1750	5,500**
26-Apr-06 18-Jul-06 17-Oct-06 17-Jan-07 20-Dec-04	<1.0 <1.0 <1.0	0.74 J <1.0 <1.0	<1.0 <1.0	<1.0	I .	<1.0		<5	NA NA	NA NA	NA NA	NA NA	2.1 J	NA NA	NA.	NA	NA NA	NA NA	<5.0	NA NA	NA NA	NA
18-Jul-06 17-Oct-06 17-Jan-07 20-Dec-04	<1.0 <1.0	<1.0 <1.0	<1.0	ı	<1.0		<1.0	<1.0	<1.0	<1.0	<0.057	<1.0	2.2	<1.0	<1.0	<1.0	U	<1.0	<1.0	<1.0	<1.0	<10
17-Oct-06 17-Jan-07 20-Dec-04	<1.0	<1.0	1	Í <1∩		<1.0	<1.0	<1.0	<1.0	<1.0	NA NA	<1.0	1.9	<1.0	<1.0	<1.0	0.33 J	0.48 J	2.3	0.33 J	2.3	<10
17-Jan-07 20-Dec-04	1		<1.0	1	<1.0	<1.0	<1.0	<1.0	<1.0	NA NA	<0.005	<1.1	2.2	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	NA.
20-Dec-04	<1.0	<1.0	1	. <1.0	<1.0	<0.5	<1.0	<1.0	<1.0	NA.	<0.005	<0.50	1.6	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
			<1.0	<1.0	<1.0	<0.5	<1.0	<1.0	<1.0	NA	<0.005	<0.50	1.9	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
12-Jan-06	<5	2.1 J	<5	NA NA	NA NA	NA NA	<5	<5	NA NA	NA	NA NA	NA NA	<0.5	NA NA	NA NA	NA NA	NA NA	NA NA	<5.0	NA NA	NA NA	NA
	0.92 J	9.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	· NR	<1.0	U	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	<10
26-Apr-06	2.0	14	<1.0	. <1.0	<1.0	<1.0	0.74 J	<1.0	<1.0	<1.0	NA NA	<1.0	0.65 J	<1.0	<1.0	<1.0	<1.0	2.3	13	2.0	14	<10
19-Jul-06	2.1	13	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	NA NA	<0.005	<0.50	<1.0	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	NA.
17-Oct-06	<1.0	6.6	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	NA	<0.005	<0.50	<1.0	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
17-Jan-07	<1.0	5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	NA	<0.005	<0.50	<1.0	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
21-Dec-04	18	6	1.1 J	NA NA	NA.	NA NA	3.5 J	5	NA NA	NA	NA NA	NA NA	<0.5	NA	NA NA	NA	NA NA	NA NA	2.1 J	NA	NA .	NA .
13-Jan-06	280	91	12	<3.6	1.9 J	<3.6	83	<3.6	<3.6	4.0	NR	<3.6	3.3 J	<3.6	<3.6	<3.6	<3.6	<3.6	<10	<3.6	<3.6	<36
26-Apr-06	250	82	10	<4.0	1.7 J	<4.0	58	<4.0	<4.0	2.5 J	NA NA	<4.0	2.2 J	<4.0	<4.0	<4.0	<4.0	3.2 J	18	3.8 J	24	<40
18-Jul-06	270	120	9.9	<5.0	<5.0	<2.5	50	<5.0	<5.0	NA	<0.005	<2.5	<5.0	<25	<5.0	<5.0	<5.0	<2.5	<5.0	<5.0	<5.0	NA.
17-Oct-06	210	130	7.8	<5.0	<5.0	<2.5	48	<5.0	<5.0	NA	<0.005	<2.5	<5.0	<25	<5.0	<5.0	<5.0	<2.5	<5.0	<5.0	<5.0	<50
17-Jan-07	160	120	5.9	<1.0	1,4	1.0	28	<1.0	<1.0	NA	<0.005	<0.5	2.1	<5.0	<1.0	<1.0	<1.0	<0.5	<1.0	<1.0	<1.0	<10
21-Dec-04	804	1,200	12	NA	NA NA		81	6.3	NA .	NA	NA	NA NA	4.6 J	NA	NA NA	NA	NA NA	NA	51	NA NA	NA NA	NA
13-Jan-08	43	1,600	<25	<25	<25	<25	29	8.3 J	<25	<25	NR	<25	<25	<25	<25	<25	<25	<25	<25	<25	<25	<250
27-Арг-06	1,200	1,300	13 J	<17	<17	<17	94	<17	<17	<17	0.036	<17	<17	<17	<17	<17	<17	<17	10 J	<17	<17	<170
19-Jul-06	740	790	<10	<10	<10	<5.0	62	<10	<10	NA	0.025	<5.0	<10	<50	<10	<10	<10	<5.0	<10	<10	<10	NA
18-Oct-06	1,400	1,400	15	<1.0	1.7	4.8	140	6.7	<1.0	NA	0.032	<0.50	5.8	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
21-Feb-07	10	1,300	<1.0	<1.0	6.8	<0.5	46	16	<1.0	NA	<0.005	<0.5	7	<5.0	<1.0	<1.0	<1.0	<0.5	<1.0	<1.0	<1.0	<10 L
20-Dec-04	227	42	2.2 J	NA NA	NA NA	NA NA	14	<5	NA NA	NA NA	NA.	NA NA	1.5 J	NA NA	NA NA	NA	NA.	NA	<5.0	NA NA	NA	NA
13-Jan-06	250	46	4.2	<2.9	0.99 J	<2.9	14	<2.9	<2.9	<2.9	NR	<2.9	1.7 J	<2.9	<2.9	<2.9	<2.9	<2.9	<2.9	<2.9	<2.9	<29
27-Apr-06	190	44	3.0	<2.5	<2.5	<2.5	15	<2.5	<2.5	<2.5	<0.005	<2.5	<2.5	<2.5	<2.5	<2.5	<2.5	4.5	20	2.5	16	<25
19-Jul-06	45	16	<1.0	<1.0	<1.0	<5.0	2.9	<1.0	<1.0	NA NA		<0.50	<1.0	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	NA
18-Oct-06	190	55	4.9	3.0	1.6	3.6	26	<1.0	<1.0	NA j	<0.005	<0.50	1.4	<5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
17-Jan-07	110	47	2.4	<1,0	<1.0	<0.5	2.9	<1.0	<1.0	N/A	<0.005	<0.5	1.2	 <5.0	<1.0	<1.0	<1.0	<0.50	<1.0	<1.0	<1.0	<10
20-Feb-07	1.4	570	<1.0	<1.0	1.3	<0.5	21	2.7	<1.0	NA	<0.005	<0.5	1.7	<5.0	<1.0	<1.0	<1.0	<0.5	<1.0	<1.0	<1.0	<10
	20	15	<1.0	<1.0	<1.0	<0.5	4.8	<1.0	<1.0	NA	<0.005	<0.5	2.4	<5.0	<1.0	<1.0	<1.0	<50 .	<1.0	<1.0	<1.0	<10 L
27-Apr-06 19-Jul-06 18-Oct-08 17-Jan-07		190 45 190 110	190 44 45 16 190 55 110 47	190 44 3.0 45 16 <1.0 190 55 4.9 110 47 2.4 1.4 570 <1.0	190 44 3.0 <2.5 45 16 <1.0 <1.0 190 55 4.9 3.0 110 47 2.4 <1.0 1.4 570 <1.0 <1.0	190 44 3.0 <2.5	190 44 3.0 <2.5	190 44 3.0 <2.5	190 44 3.0 <2.5	190 44 3.0 <2.5	190 44 3.0 <2.5	190	190	190 44 3.0 <2.5	190 44 3.0 <2.5	190	190	190	190	190	190	190

Chemical abbreviations:

BDCM =

Tetrachloroethene. PCE = TCE = Trichloroethene. 1,1,1-TCA = 1,1,1-trichoroethane. 1,1,2-TCA = 1,1-DCA = 1,1,2- trichoroethane. 1,1-Dichlorethane. 1,2-DCA = 1,2 Dichloroethane. 1,1-DCE = cis-1,2-DCE = Trans-1,2-DCE = 1,1-Dichloroethene. Cis-1,2-Dichloroethene. Trans-1,2-Dichloroethene. 1,1,2-TCFE = 1,1,2-Trichlorotrifluoroethane. 1,2,3-TCP = 1,2,3-Trichloropropane Vinyl Chloride. MC = Methylene Chloride. DBCM = Dibromochloromethane.

Bromodichloromethane.

Notes:
Results in excess of MCL are in bold. Analyses for the current quarter are italicized.
MCL = Maximum Contaminant Level
MCL = Maximum Contaminant Level

Not detected at reporting limit.

Analyte exceeded quantitation limit.

Not analyzed.

NR =

Not analyzed.

Sample was collected as planned. Due to laboratory error, there are no 1,2,3-TCP results available for SW-2 through SW-5.

1,2,3-Trichlorpropane analyzed by EPA Method 524 SIM

The results of the initial analysis for this sample was greater than the linear calibration range for the analyte and one or more analysis were performed using greater dilutions.


California Region 9 PRG (October 2004) for tap water. MW-4A installed January 7, 2007. SW-4 Decommisioned January 2007. MW-6 installed December 2007.


2 =


MW-7 installed December 2007.


- False positive and qualified as undetected due to blank contamir
 Estimated value. Analyte detected at a level less than the Reporting Limit (RL) and greater U = J =
 - than or equal to the Method Detection Limit (MDL).
- Analyte detected in Method Blank.
- The RPD exceeded the method control limit due to sample matrix effects.
 - the individual analyte QA/QC recovenes, however, were within acceptance limits.


FIGURES

















APPENDIX A

GROUNDWATER SAMPLING FORMS WELL DEVELOPMENT FORMS

Former Weber Aircraft Facility Field Data Sheet* Groundwater Monitoring 1st Quarter 2007

2.20.07

Field Sampler: 8/1: - feet

Dan + Justin

^{*} An individual Groundwater Sampling form names to be completed for each well monitored

	Previous Qtr DTW:		Depth to Group below top of cas		Total Depth	Casing Diameter	Notes
Well ID	4th 2006	Time	1st Reading	2nd Reading	(ft BTOC)	(Inches)	
SW-01	227,35	D835	726.26	226.76	263.10	6	
SW-02	221.42	0845	21.9.50	219.50	249.29	6	broken luckenjyphy, still locus knowly,
SW-03	228.15	0910	724.37	2243F	258.85	ð	
MW-4A	223.80	0925~	211.49	718.49	26928	2	
9W-05	2?4.52	0930	270.37	220. 37	259.22	6	
MW-6		0865	222-03	722.03	261.09	2	
MW-7		20905	224.79	22478	269.40	2	

Mail Construction Details

Well ID	Screened Interval (ft. bgs)	Blank Casing Interval	Top of Casing Elevation (ft.msl)	Ground Surface Elevation (ft.msl)
3W-01	207-262	237-242	711.8	712.66
SW-02	190-245	220-225	702.14	702.4
SW-03	200-255	230-235	697.69	898.32
MW-4A	210-270	210-GS		
8W-05	196-258	228-229	692.65	693.03
MW-6	200-260	200-G5		
MW-7	212-272	212- GS		

Former Weber Aircraft Facility

BALL AND 4, 500 . 16 247 ي المالي الماليا - 2

GROUNDWATER SAMPLING FORM: 1st Quarter 2007

Well Id. SW-1

Project # 40641

Well Types Continue Extraction Other: MCNITOR

Recorded By:

Perse Mettour Baller-Type:		· aon	··y	Purce Volume Casing Biarrote: (3 in Inches): 5					Semple Date: <u>Ci-17-07</u>		
Punjakg Math	ad: 1°grunctos			Total Depth of Cealing (TD in feel STOC):							
Other-Type: _				Water Level Depth (WL in Seel STOCK 1226-86					his:		
Purge Voluma (Askadarion)				Massured on: (4, -, 7, -97					<u>Direct</u> ski	e Haler	
762)-(226									Galans Contra llet	:	
Steert Time:			Seep Time:	·							
	eter Messuren									·	
Time	Appropries	Purge Flage (ginin)	Temp(C")	pH Canductivity DO (mg/L) Turkstly (m614m)			i	Remark placements			
671k	ip	븨	19.5	6.59	c. 113	5.87	: 45	41. BEN			
5 7.3 ₃	450	4	20.5	6,17	0.753	1.12	55	CI. BRN		·····	
£ 74%	40	भ	20.9	6,12	0.757	6.09	72				
: 753	120	4	21,2	1.12	0,757	5.49	54				
0505	160	ų.	20.6	6.10	0.750	6.04	15	CLEAR.			
		,		1		 * × · · · · · · · · · · · · · · · · · ·	1	101010			
	-··· -			 -	·	 	†	:			
	 			 	 	i	<u></u>	<u>. </u>			
	 				 						
	<u>:</u>	<u> </u>		:	 	ļ					
	<u>. </u>			i [
					<u> </u>		 				
			. ~			<u> </u>	 	<u> </u>			
					<u> </u>		<u> </u>				
	<u> </u>	ļ		 			·. 	-			
	ļ		···				Ļ				
	<u> </u>			<u>:</u>							
					L			_			
						•				· · · · · · · · · · · · · · · · · · ·	
							†" 	·			
Sampling Infor	anation	Pre-Fiet	d Chack	Elastiqui and Test Methods							
Sample Point Britis : Batties		(C) and (Grpc) of Consultation Preservatives.			Analysis/Comments		Hoteling	Nones			
ardered received		16461462	3			Jimits [N uni					
			7	Hier and wights	P	1-4 Cheming (17/0)		li esta			
			1	530-m: poly katile 530-m. poly katile	C. 163	Tile 22/Cem 17 Me Cimbred .rcn & No		(France)	<u>. </u>		
		2	G20-mt pely battle		Cahani (8010)		ji carinj				
				250-mi Pisulis ·		Headward Commit			' www.breigh/ggastcide		
					125-m paly bottle		Paratherin (LDV 2)		Cit care		
			كامد له الحيادة	scale radius interes.		Disselved Cayyon (_:	A hours			
				SUB-ral pay bettu		Suffee (SOET)		() stant			
			· -	<u>_</u>	140-m. VOA	<u> </u>	40-Aller methylani Tribution methylani	ne (1245) ne (1244) (124 1225);	(14 steps) 3 steps	 	
:				<u> </u>				. 1		L	



GROUNDWATER SAMPLING FORM 1st Quarter 2007

SW-2

in teach

(AES) Will (AEIH) a lunifumunougue

She Name:					,	Well Id. SW-	2				
F	Former Weber					1		Recorded	Elg:		
Aircraft Facility				Well Type Moritor Extraction Other: MONITOR							
	rcran	racii	ITY	Purus Valurae	_				•		
Bater-Type:	Purge Method Baler-Type:				E Her (C in Inches); &		Fample Cale	_ D}~	17-07		
Purnping Meth	Purfiping Method: 3' gouncles				Casing (75 in feel	втос: <u>2.4 5</u>	<u> </u>				
Other-Type;	Other-Type;				esh (WL in Sait 31	∞: <u>220</u> .	40				
							Ramba rilas				
Рима Уобила	Purqu Votume Calculation:				<u> </u>		Sample Methed: <u>Danosable Seila:</u>				
, 24	5	1-1 2	20) X (6") ² X (3) X 0.0408 =					Gellans		
	TD (feet)	<i>-</i>	W. Heed								
San iima			Stop Time:		:						
	nter Meesures		SEE HAR								
Field Parame				-			 	<u> </u>			
Тінс	Volume (gallons	Perge Rate (g/min)	ĭemp[⊏]	! рн	Conductivity (m5/cm)	DO (mgC)	Tensity	Ra-	ten yer general		
408	10	4 63%	19.2	6.34	0.622	642	9	CleAL			
918	50	4 tem	20.5	6.08	0.675	6.21	144	SI. Cl. BRI	Ž		
928	10	Hern	22.3	6.06	0:673	5.71	30	CLR	_		
9.28	110	41.00	22.3	6.10	0.669	5.57	19	c + 2	·	··	
- 1 // -3 -		11 20				-	 				
 	<u> </u>	7 384		 	:	 	·				
<u> </u>			<u> </u>	 -	·:··-	<u> </u>	 	:			
		 -		!	<u> </u>		<u> </u>				
		<u> </u>	<u> </u>		<u> </u>					·	
		<u> </u>				<u>i</u>	<u>i</u>				
		<u> </u>									
	<u> </u>						 				
ļ	·				<u> </u>			! 			
					<u>!</u>	ļ			· 		
						<u> </u>			_		
					: .	<u> </u>	<u> </u>			,	
				!]						
						:	 [···			
						<u> </u>	<u> </u>				
		' _ :	 -				ļ		 .		
<u></u>		. ———				<u> </u>	 				
		<u></u>			L						
Sampling Information Pre-Field Check		Glotti			Buttos and Tast Melhods						
Bampi	Paint	Partilias Ordered	Botflee received	[5] 324 [739	e) of Containers	Preservatives	Ana	ysia/Commerate	Molding Stmit	Notes	
6 V	6W-3			43mi YOA		HCt.	VOC1 (222)				
				1-May amber glaza 500-mi arty helt n		 	7-4 Commis (827-2 Mark) This 22/Commit Mickels (60:10/747:1)		le tamas al A spilas		
				900 ti pely laita		1	Des prod Imp & fA:		(Seemating		
					800-tipoly battle	:	Culima (80:2)		il maker		
	· · ·				175+m1 poly turbs* 253-m1 (humb=			in (7187) BOX CU 50170	(I have	· de and Mary to Plate as Lat.	
								Annre (402, 1603, 504, 61) (501.0) (8 heir: Paretimete (194-316.1) (28 sept)			
				90>mlamberglass Disselves Coppus (312.1) B ha			B hauers				
ļ	·				500-mippy grate		Su Not (930C)	- 150 5	(P LONG)		
·			40-ml VOA	L	1.2.7-Tri:Hereptop:	27 D [1628] 22]	:14 ≐⊎0	!			

14ter amber goss



GROUNDWATER SAMPLING FORM 1st Quarter 2007

Well Id. SW-5

Project # 40841

SW-5

AND WHE EN'S WHE PA

ويوا

Former	Weber
Aircraft	Facility

Respirated By: Well Type: Months: Excretion Other: MONITCR Purge Method Bater-Type Purge Volume Caping Diameter (D in instee): 8 Sample Deca 31-13 - 07 Tald: Depth of Casing (TD in feet 970C); _ 2.6 $\tilde{\mathcal{G}}$ Pumping Method: 3" grundlas Webs Level Depth [WL in feet BTOC]: 222-15 CHEET-Type: Sample Time: Massured on : Purqu Voluma Calculation: Diesaseth is Beile-260 222 x 0.0408 = 167) X (6')² Gallans Wi (feet) D (instant) Purge Volume (galons) Slop Times. Field Parameter Steasurements Cunductivity (m&cm) rge Fixty Temp (CF) ու խորոյ Turbidity 147 0.746 1,46 W 17 1025 CLEAR 50 1836 CIERL ि 45 21 10 FS 130 11 6% 170 clear. Sempling Information Pre-Field Cheeds Poties and Test Mathods Bottlee **Bottles Europie Peint** Artalysia/Comments [8] 으로 [504] 후 도미라시아스 Preservatives Mates received 61A-1 任・町 プレヘ 1-4 Cicago v (8276 B:M) GCD-TI poly outdo 711 + 22/Cam : 7 Metab (6010/7471) / E menti d (CP CO) Seemmodel & non: hypotess: (- K manak MCDetti proj bertin : 900-mi paly antin Codene #8010! १२५-ला ५और अध्यक्ति Heravales Cremius (7.34) Acient (NOZ NOS, BC4, D.; (500 c) 253mi Fledi: (4) head 122-m) patr 2001s Peistra air ILPA 3:4.1) 720 134.1 Dissolved Copper (782.1) E hours Buttie (5083) ettes yea im cas (terr) 4D-HI VOA :.25-Truliurepropere (924.2) (14 EVery 1-iter under ##45 WHAT STREET SHOULD STREET STREET 7450

1 - Her ambergiess

Darms-umor (Net of DL NOP 3)



GROUNDWATER SAMPLING FORM 1st Quarter 2007

CIM-3

B heurs

(3v mile) | E40 4444 | i.i. 4484)

THE LANGE OF BRIDE

Dissover Charges (250.1)

1,2,5-TricHooperpoon (5247)

N-Xtreatmethylunine (NENA) (EFA 102EA) ClaumaFu ans (Method CL/#2.2)

Siche (BXE)

Site Name;				Well Id. SW-3					244-2		
Former Weber				Project # 40B41					Section de la S	∃y:	
-					Vini: Typa; Mont	lar Extraction Othe			-		
Aircraft Facility				Purge Volume							
Beiler-Typs:	Dailer-Type:				er (D in mches): 6			Sampl	e Dates <u>⊅1 *</u>	13.07	
Auriging Male:	od: 3' gryndigs			Total Depth of Gaung (TO In feel BTDD): 255					_	_	
Caher-Type:						oc; <u>2.21</u>	<u>. ۱ -55</u>	Semple Time: 1300			
Purge Volume Calculation:				Meesured an:					t: <u>Ginasanbla</u>	Befler	
(755)- (751- TD feet) /A1 feet				X (6") ² X (3) X 0.0408 = 15 C Denches #Voz Purge Velume (patients)					Gerians Geregated	150	
Start Times			Etop Time:								
Field Paramo	ter Measuren	nen ts		,				 			
Titrus	Volume (gallens)	Purge Rus (symin)	- industry	pH.	Gerelueffelly (mfMcm)	DO (mg/L)	Turbidity		ilomarka/Camm	ents	
3200	10	4	ું (ળ, 6	6.38	. გიი	8.50	29	St. Ci. &	ندي		
3210	50	4	20.5	6.28	.797	6.23	67	11	•		
7226	ଜୀତ	냭	20.8	6.19	.799	6.09	23	λί			
12.50	135	ાં	20.4	6.15	,799	6,10	10	cier			
12:35	150	u,	20.4	6:14	1398	6.11	li.	H			
			<u> </u>				:	:			
				!							
<u> </u>		:		:			<u> </u>	i			
							<u> </u>	i			
		: :	<u> </u>	:	:		<u> </u>	<u> </u>			
:	· · · · · · · · · · · · · · · · · · ·		l i		<u> </u>		<u> </u>		•		
	<u> </u>			.· • . • • . • •							
	<u> </u>	<u> </u>	1		! 						
<u> </u>			 		<u>. </u>						
<u> </u>			<u> </u>								
			•								
			$\neg \neg$			· · · · · · · · · · · · · · · · · · ·					
										,,,,,	
			<u> </u>								
Sampling Entermation Pre-Field Check		ld Check	Bortles and Te				est Methods				
Sample Point Buttles Buttles ordered reported						Ana	lysis/Conzuents	Halding :	Notes		
SW-3				43mi ₩∆A	HCL	VOC . (6190)		1400			
	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			<u> </u>	:-ilar on:barglass	ļ .	1-4 Change (6070	-,	iqus II, (Alsen B.	-	
<u> </u>					530 ml 39 y botile h30-ml pery hadia			am (7 Mela (1965/747)) (Ion & Wingensen (2010)		— .·ч- ·	
					520-r:i pu y loci v				.% sveske) ∰ cventraj		
					125-mi paly belt e	Herroelert Chromiu				derel Barb Miler Là	
			ļ		250-대 Phris	:An ora (MOF, NCR)		BOM, CLJ (200 0)	all telepon		

Gió-zi enter gissa

570 - I poly bolt ≥

1-Per amber gless

if - (far ember glass

40m 1854

WELL GAUGING DATA

Project # 07022C	Dete	2/20/07	Client $\mathcal{Z}_{\mathcal{U}}$	rus AcDonnell
Site <u>3000</u>	pan Ferna	udo Blixi	B_{00}	bauk

		Well Size	Sheen 7				Depth to water	17, 176, 3, 3, 3, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4,	Survey Point: TOB or	
Well ID	Time 922	(in.) 2	Odor	Liquid (ft.)	Liquid (tt.)	(ml)	(n.) 218149	bottom (ft.) 269-28	TOC	Notes
MW-le		2					222.03	261.09		
uw-7		2					224.78	la de la Caracia. Calmanta		
<u>6</u> w-1 5u)-2		6					211e,71o 219,50			
5w-3		6					224137			
5u>-5	930	6					220:37	259.22		

		WEL	L DEVEL	OPMENT	DATA S	HEET		
Project #:	07022	O. PKI		Client:	Client: Bi M.			
Develope	r: Dan V	5, / 2,	estin Me	Date Developed:				
	MW.41			Well Dian	neter: (circle	e one) (2) 3 4 6		
	ll Depth:			Depth to V	Water:			
Before		After		Before 21	8,49 Aft	er		
Reason no	ot develop	ed:		If Free Pro	oduct, thick	ness:		
Additiona	l Notation	ns:						
(12 x (c where 12 = in /	neter (in.) 416		Well dia. VC 2° # 0.1 3° # 0.2 4° # 0.6 6° # 1.6 10° # 4.0 12° = 6.8	55 55 57 7 7				
81/		X				81.0		
1 Case	Volume		Specifie	d Volumes	=	gallons		
Purging De	vice:	Type of Insta		p Watera		Electric Submersible Positive Air Displacement Fung		
TIME	TEMP (F)	рН	Cond. (mS or (AS)	TURBIDITY (NTUs)	VOLUME REMOVED:	NOTATIONS:		
1138	76,4	7.62	833.1	2/000	4			
1234	74.4	7.41	818,6	71000	10			
1314	Tle, 3	.7.35	803.4	71000	15			
1348	75.8	7.24	814,6	>1000	20			
1416	74.9	7.28	791.3	>1000	25			
1440	73.2	7,29	718.6	71000	30			
1505	and and a street				35			
1534	72.1	7.27	768,2	7/000 350	40			
1406	71.8	7.23	764,5	280	45			
1636					50			
1000				469				

60

45

81

32

Gallons Actually Evacuated:

761:7

7.15

If yes, note above.

70.4

Did Well Dewater? No

Well I.D. 100 4A	PAGE 2 OF 2	
Project #: 070220 DKI	Client: Béll	

TIME	TEMP (F)	рН	Cond. (mS or 🌠)	TURBIDITY (NTUs)	VOLUME REMOVED:	NOTATIONS:
1834	70.6	7.17	759.4	30	70	
1904	70:7	7.14 wwe ap	759.4 757.6	38	75	
	+ Val	uiue ak	1 1" to	bing@	69	
)	8/a to	tal
					\mathcal{L}	
				-		
						·
			·			·
		-				

Project #: 07027	20. PK/				Client:	BEM	
Developer: Dan	tin.	11.		Date Developed: 2/20/07			
Well I.D. uw-				Well Dia	Well Diameter: (circle one) (2) 3 4 6		
Total Well Depth:					Depth to	Water:	
Before 261.09	After				Before 2	22.03	After
Reason not develo	ped:				If Free Pr	oduct, thi	ickness:
Additional Notation	ons:						
Volume Conversion Factor (V 1/2 x (d ² /4) x it) /231 where 12 = in / foot d = diarneter (in.) x = 3.1416 231 = in 3/ga1	CF)·	Well dia 2° 3° 4° 6° 10°' 12°	# # # # # # # # # # # # # # # # # # #	VCI 0.16 0.37 0.65 1.47 4.08 6.87	5 7 5 9		(02.8)
1 Case Volume			Spec	ified	l Volumes	=	gallons
Purging Device:	Type of Inst	Sucti	on P ump	•)		Electric Submersible Desitive Air Displacement

TIME	ТЕМР (F)	рН	Cond. (mS or AS)	TURBIDITY (NTUs)	VOLUME REMOVED:	NOTATIONS:
1512	67.8	6.96	7.86	>1000	100	Set pump @ 250'
1514	70.7	7.32		71000	12a	
1520	70.9	7.29		>1000	180	
1524	711	7.36	749.5	71000	224	
1528	71.2	7.34	736,0	71000	Llag	
1531	71.2	7.31	737.0	255	30 g	
1534	71.1	7.42	738.0	238	34.	bet pump@ 257,5'
1537	71.1	7.46	740,0	194	389	
1540	71.2	7.38	741.3	144	420	
1543	71.1	7.42	741.6	134	460	
1544	71.1	7.46	741,4	88	50a	
1549	71.1	7.41	741,8	125	54a	··
1552	71.1	7.40	742.1	59	58a	
Did Well Dev	valer? NO	lf yes, note abo	ve.	Gallons Actually	y Evacuated:	86

 Well I.D. 070220-Pkt
 Mw-6
 PAGE 2 OF 2

 Project #: 070220-Pkl
 Client: B&M

	1		Cond.		I	
TIME	TEMP (F)	pН	(mS or (S)	TURBIDITY (NTUs)	VOLUME REMOVED:	NOTATIONS:
1665	71.1	7,47	740.6	44	62g	
1558	71.0	7,38	740.7	30	669	
1601	70,9	7.32	739,6	23	70 g	
1404	70.9	7,37	737,3	14	749 784 824 864	
1407	71.1	7.41	737.6		78g	
1610	71.0	7.40	737.1	9	829	
1613	71.0	7.41	736.4	9	860	
		i				
· · · · · · · · · · · · · · · · · · ·						
		:				

						•		
Project #:	07022	0. PK1				Client:	BEM	
		4. / Jus	tiu,	M.		Date Deve	loped:	2/21/07
	.uw-7	··· /				Well Dian	neter: (circl	
Total Wel	•					Depth to V	Vater:	
Before Z	109.40	After				Before 22	74.78 Aft	ter
	ot develop	oed:				1 .	duct, thick	
Additiona	l Notation	ns:						
	ersion Factor (VCI	F) ⁻	Well dia.		VC	-		
	d ² /4) x π) /231	•	3.	•	0.10			
where 12 = in /			3" an	4.	0.37			
	racı neler (in.)		6"		1.47			
n = 3.14			10"	-	4.08			
231 = in 3			12"	•	6.87		·	
7,	1	X			0			71.0
1 Case	Volume	·	S	peci	fied	d Volumes	=	gallons
Purging De	vice:	۵	Bailer				<u> </u>	Electric Submersible
1 01 D 0	7100.		Suction		ומוי	n		Positive Air Displacement
		-	Ductio))] l	41114	J		LOSITIAC VII DISDIRCCIICIII
		Type of Insta	alled Pi	ump	ı			
		Other equipr						
		Omer 54-17-						
			Co	ond.	_	TURBIDITY	VOLUME	·
TIME	TEMP (F)	pН	(mS c	or 🕻	3)	(NTUs)	REMOVED:	NOTATIONS:
-714	710	7,0	ش. بر			70	71	21100

TIME	TEMP (F)	pН	Cond. (mS or (S))	TURBIDITY (NTUs)	VOLUME REMOVED:	NOTATIONS:
841	71.0	7.12	674,4	70	7.5	Pump bet @ 250
847	71.8	7.16	683.6	48	14.5	
853	72.1	7.24	484.1	35	21.5	
859	72.0	7.31	686,6	72	28,5	
904	72.0	7,41	687.8	12	35,5	
910	71.7	7.46	487.3	39	43.0	Pump bel @ 257
916	71.9	7.61	686.7	8'	50.0	
922	72.2	7,56	687.8	7	57.0	
928	71.7	7.58	688.6	2	64,0	
934	71.6	7,61	688,2	Z	71.0	
940	11.8	7.64	688.7	2	1810	
Did Well Dev	vater? UD	If yes, note abo	ve.	Gallons Actually	y Evacuated:	78

TEST EQUIPMENT CALIBRATION LOG

PROJECT NAM	NE			PROJECT NUMBER			
EQUIPMENT NAME	EQUIPMENT NUMBER	DATE/TIME OF TEST	STANDARDS USED	EQUIPMENT READING	CALIBRATED:	TEMP.	INITIALS
Mysou L Ultrametes	6202110	2/20/01 800	Ph 4,7,10	410, 7.0, 10.0	yes	57.30+	THE
11 11	10 11	11 11	Coud 3900 NS	3900,05	yes	58,5°F	V
Myroul Ultramote,	6202110	2/21/07	ph 4,7,10	40,70,100	yw	58.1°F	De la companya di managaran di
11 11	11 11	11 11	pir 4,7,10	4.0, 7.0, 10.0	yes	59.4°F	·
				·			
,							
			,				
		·					

APPENDIX B

ANALYTICAL REPORTS AND CHAIN OF CUSTODY DOCUMENTATION
Title 22/CAM 17 Metals
VOCs
Dioxins/Furans

UNSCANNABLE MEDIA

To use the unscannable media document # <u>2240227</u> contact the Region IX Superfund Records Center

APPENDIX C

BURNS & MCDONNELL'S QA/QC REVIEW OF ANALYTICAL DATA



Date: March 17, 2007

To: Gary Messerotes

From: Sharon Shelton

Re: QA/QC Review of Analytical Data

First Quarter 2007 Groundwater Sampling Event

Burns & McDonnell Project Number 40641 (Former Weber Aircraft)

Groundwater samples were collected in January and February 2007 from seven monitoring wells associated with the Former Weber Aircraft facility. Samples were analyzed by Test America of Irvine, California (formerly DelMar Analytical) for the following parameters:

Analysis	Method
Groundwater Samples	
Volatile Organic Compounds (VOCs)	SW-846 Method 8260B
1,4-Dioxane	SW-846 Method 8270C with
<u> </u>	Selective Ion Monitoring (SIM)
N-Nitrosodimethylamine (NDMA)	EPA 1625M
1,2,3-Trichloropropane	EPA 504.1
Title 22 / CAM 17 Metals	
Arsenic, antimony, barium, beryllium, cadmium, chromium,	SW-846 Method 6010B
cobalt, copper, lead, molybdenum, nickel, selenium, silver,	
thallium, vanadium, and zinc	
Mercury	SW-846 Method 7470A
Dissolved Metals	
Dissolved Iron	SW-846 Method 6010B
Dissolved Manganese	
Hexavalent Chromium	SW-846 Method 7199
Cations	
Calcium, magnesium, potassium, and sodium	SW-846 Method 6010B
Anions	
Chloride, Nitrate, Nitrite, and Sulfate	EPA 300.0
Perchlorate	EPA 314.1
Sulfide	SW-846 Method 9034
Dissolved Oxygen	EPA 360.1
Dioxins and Furans (Wells SW-3, SW-5, MW-4A, MW-6, and MW-7)	DLM02.0

The following data sets were reviewed in support of this investigation:

		Samples	
st America	01/17/2007	SW-1, SW-2, SW-3, and SW-5	
st America	02/20/2007	MW-6	
st America	02/21/2007	MW-7	
st America	02/21/2007	MW-4A	
	est America est America est America	est America 02/20/2007 est America 02/21/2007	



Memorandum March 17, 2007 Page 2

The quality assurance/quality control (QA/QC) results in association with the samples were evaluated for achievement of any method-specific QA/QC criteria. Data qualifiers, when appropriate, were assigned according to the guidelines presented in USEPA Contract Laboratory Program National Functional Guidelines for Organic Data Review (NFGO), 1999; USEPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review (NFGI), 2004; or USEPA National Functional Guidelines for Chlorinated Dibenzo-p-Dioxins and Chlorinated Dibenzofurans Data Review, 2005. The QA/QC review results are discussed below. Table 1 presents a summary of data qualifiers that were assigned during the data review.

- 1. Chain-of-Custody The chain-of-custody (COC) forms were appropriately signed.
- 2. Requested Analyses Completed All samples were analyzed as requested on the COC.
- 3. <u>Holding Times</u> Samples for dissolved oxygen analysis were submitted to the lab outside of the 15-minute holding time. The laboratory analyzed these samples within 24-hours of collection. To indicate potential bias in the data, the dissolved oxygen results for all samples were qualified as estimated (J*) as indicated on Table 1.

All other sample preparation and analyses were performed within the appropriate holding times.

- 4. Sample Preservation No problems were noted with sample preservation.
- 5. <u>Laboratory Method Blanks</u> Method blanks were reviewed to determine the potential for sample cross contamination due to laboratory handling. With the exceptions noted in the following paragraphs, target compounds were not detected in the method blanks.
 - NDMA was detected in the method blank for QC Batch 7A18113 in data report IQA1645. Since NDMA was not detected in the associated field samples, crosscontamination was not a concern. No data required qualification.
 - Calcium was detected in the method blanks for QC Batches 7B23071 (data report IQB2363) and 7B21160 (data report IQB2138). Since calcium was detected in the associated groundwater samples at concentration in excess of five times the blank value, any impact from sample cross-contamination was minimal. No data required qualification.
 - Trichloroethene was detected in the method blank for QC Batch 7B26028 in data report IQB2138). Trichloroethene was not a target VOC for the sample associated with this blank. Therefore, the potential for sample cross-contamination was not a concern. No data required qualification.
- 6. <u>Trip Blanks</u> Trip blanks were submitted with the VOC and 1,2,3-trichloropropane samples. Trip blanks were used to determine the potential for sample cross contamination due to shipping and handling. Target compounds were not detected in the trip blanks, and cross contamination was not an issue.



Memorandum March 17, 2007 Page 3

- 7. Surrogates Surrogates are added for organic analyses. Surrogates are compounds not normally found in the environment that are added (spiked) into samples and analyzed for percent recovery (REC). Maximum and minimum limits on the REC are set by the laboratory for the method used. Unless noted in the following paragraph, surrogate RECs were within QC limits.
 - 1,4-Dioxane The sample collected from monitoring wells SW-5 was diluted by a factor of 250 to bring concentrations of 1,4-dioxane within the calibration range. Diluting the sample resulted in loss of the surrogate spike, and analytical accuracy could not be assessed using the surrogate results. Instead accuracy was assessed by review of the laboratory control sample (LCS) results. Data qualification was not required.
- 8. Laboratory Control Sample (LCS)/Laboratory Control Sample Duplicate (LCSD) The LCS contains a matrix similar to that of the sample that has been spiked with known concentrations of target analytes. The LCS is prepared and analyzed by the same method as the samples. As a measure of analytical accuracy, the results of the LCS are compared against the known analyte concentrations in the spike to determine REC. The purpose of the LCS is to determine the performance of the laboratory with respect to analyte recovery, independent of field sample matrix interference. The LCSD is a duplicate preparation and analysis of the LCS. Results of the LCS and LCSD are compared to each other to determine analytical precision using the relative percent difference (RPD). Unless noted in the following paragraph, LCS and/or LCSD results were within QC limits.

The following constituents exhibited elevated LCS RECs in one or more QC batches:

Analysis	QC Batch	Constituent	Data Package	
VOC	7A2105	Isopropylbenzene	IQA1645	
VOC	7B28006	Acetone	IQB2363	
	7B20831		IQB2138	
	7B24017		IQB2280	
	7B26007			
VOC	7B26007	1,1,2,2-Tetrachloroethane	IQB2280	

Elevated RECs indicates potential high bias in the data. Since these constituents were not detected in the associated samples, high bias was not a concern. No data required qualification.

- NDMA QC Batch 7B22088 (data package IQB2363) LCSD REC of NDMA was below
 QC limits and the RPD was elevated, which suggest problems with analytical accuracy
 and precision. The laboratory performed a corrective action by reanalyzing the LCSD,
 and all results were within QC limits. The data report indicated that inaccurate spiking of
 the LCSD likely caused the problem. Since corrective action addressed the issue, no data
 required qualification.
- 9. Matrix Spike and Matrix Spike Duplicate (MS/MSD) MS and MSDs are typically run for organic and inorganic analyses to determine potential matrix effects upon analyte accuracy and precision. A sample is split into three portions (original, MS, and MSD), and a known



Memorandum March 17, 2007 Page 4

amount of a target analyte is added (spiked) to two portions (MS and MSD) of the sample. The results are compared against the unspiked portion of the sample for REC of the spike and potential matrix effects. Additionally, the results are compared against each other using a RPD to determine reproducibility.

The following site-specific MS/MSD analyses were performed:

Site Samples used for MS/MSD Spiking						
Analysis	Sample Spiked for MS/MSD	Data Package	QC Batch			
Chromium, hexavalent	SW-5	IQA1645	7A18061			
Sulfide	SW-1	IQA1645	7A19099			
Mercury	MW-4A	IQB2363	7B23077			
Sulfide	MW-6	IQB2138 IQB2363 IQB2280	7B26119			
. VOC	MW-6	IQB2138	7B26028			
Mercury	MW-6	IQB2138	7B21084			
Dissolved Iron/Dissolved Manganese	MW-6	IQB2138	7B21139			
Dissolved Iron/Dissolved Manganese	MW-7	IQB2280	7B22137			

With the exception noted in the following paragraph, no problems were noted with the site-specific MS/MSD analyses.

 VOC QC Batch 7B26028 – Elevated MSD RECs were noted for bromodichloromethane, chloromethane, 1,2-dichloropropane, isopropylbenzene, and toluene. The elevated RECs suggest the potential for high bias due to matrix interference. Since none of these constituents were detected in parent sample MW-6, high bias was not a concern. No data required qualification.

In addition, the laboratory provided MS/MSD results that were performed using samples that were not collected from the Site. Since these samples would not be representative of potential matrix interference caused by site conditions, they were not used in the review of the data.

- 10. <u>Detection and Quantitation Limits</u> Table 2 presents the samples that required dilution in order to bring target analyte concentrations within the calibration range of the instrument and/or to account for matrix interference. For multi-constituent analyses (i.e., VOCs), the dilution resulted in elevated reporting limits for undetected compounds.
- 11. <u>Conclusion</u> No data were rejected as a result of the QA/QC data review. Table 1 presents a summary of data qualifiers assigned during the QA/QC review. The data should be used, as qualified, in reporting the results of this investigation.

Attachment
Table 1 – Data Qualifiers
Table 2 – Sample Dilution

Table 1
Data Qualifiers
Former Weber Aircraft

Laboratory	Analysis	Target	Qualifier	Reason for
Number	Analysis	Analyte	Added	Qualification
IQA1645-01	WQUAL	Dissolved Oxygen	J*	Received and analyzed by lab outside of 15 minute holding time.
IQA1645-02	WQUAL	Dissolved Oxygen	J*	Received and analyzed by lab outside of 15 minute holding time.
IQA1645-03	WQUAL	Dissolved Oxygen	J*	Received and analyzed by lab outside of 15 minute holding time.
IQA1645-04	WQUAL	Dissolved Oxygen	J.	Received and analyzed by lab outside of 15 minute holding time.
IQB2363-01	WQUAL	Dissolved Oxygen	J*	Received and analyzed by lab outside of 15 minute holding time.
IQB2138-01	WQUAL	Dissolved Oxygen	J⁺	Received and analyzed by lab outside of 15 minute holding time.
IQB2280-01	WQUAL	Dissolved Oxygen	J*	Received and analyzed by lab outside of 15 minute holding time.
	Number IQA1645-01 IQA1645-02 IQA1645-03 IQA1645-04 IQB2363-01 IQB2138-01	Number Analysis IQA1645-01 WQUAL IQA1645-02 WQUAL IQA1645-03 WQUAL IQA1645-04 WQUAL IQB2363-01 WQUAL IQB2138-01 WQUAL	Number Analysis Analyte IQA1645-01 WQUAL Dissolved Oxygen IQA1645-02 WQUAL Dissolved Oxygen IQA1645-03 WQUAL Dissolved Oxygen IQA1645-04 WQUAL Dissolved Oxygen IQB2363-01 WQUAL Dissolved Oxygen IQB2138-01 WQUAL Dissolved Oxygen	NumberAnalysisAnalyteAddedIQA1645-01WQUALDissolved OxygenJ*IQA1645-02WQUALDissolved OxygenJ*IQA1645-03WQUALDissolved OxygenJ*IQA1645-04WQUALDissolved OxygenJ*IQB2363-01WQUALDissolved OxygenJ*IQB2138-01WQUALDissolved OxygenJ*

J* = Qualified as estimated during the data review.

WQUAL = Water Quality

Table 2 Sample Dilution Former Weber Aircraft

Sample		Laboratory		, , , , , , , , , , , , , , , , , , , ,	Dilution
Name	Lab	Number	Analysis	Parameter Parameter	Factor
SW-1	Test America - Irvine, CA	IQA1645-01	INORG	Chloride, Nitrate-N, and Sulfate	20
SW-2	Test America - Irvine, CA	IQA1645-02	INORG	Chloride, Nitrate-N, and Sulfate	20
SW-3	Test America - Irvine, CA	IQA1645-04	INORG METAL	Chloride, Nitrate-N, and Sulfate Chromium VI	20 20
SW-5	Test America - Irvine, CA	IQA1645-03	SVOC INORG	1,4-Dioxane Chloride, Nitrate-N, Nitrite-N, and Sulfate	250 20
MW-4A	Test America - Irvine, CA	IQB2363-01	INORG	Chloride, Nitrate-N, and Sulfate	10
MW-6	Test America - Irvine, CA	IQB2138-01	INORG VOC	Chloride, Nitrate-N, and Sulfate Trichloroethene	10 5
MW-7	Test America - Irvine, CA	IQB2280-01	INORG	Chloride, Nitrate-N, and Sulfate	5

INORG = Inorganic Constituent

VOC = Volatile Organic Compound

SVOC = Semivolatile Organic Compound

